


Performance Update: S1.1 - R78


- Restarted during the CM
- Completed 340K since, 670K total.
- After restarting there were quadrature problems on the odd pulse (50 total). These seem to have disappeared for the last day of running.

S1.1(R78) - Acceleration to SP1 (m s^{-2})



- Starting position has also broadened...
- Now seeing 10 starting positions (1.5mm)
- For the faily performance update see:
http://www.hep.shef.ac.uk/research/mice/uploads/S11/targetPerformance_EndShift__2012_10_23_11_10.pdf

S1.1(R78) - Start Pos. BCD (mm)



Quadrature Glitch During startup

- During start-up there was a quadrature glitch which caused S1.1 to be dropped....

